

The groove machined into the back of the original race 'A' is much deeper and wider than the new race 'B' shown fitted to the crank.

This does not allow the jaws of the bearing removal tool to have sufficient grip to pull the races off the shafts.

